



DC: 20190312v2

Thank you for purchasing the **HP Tuners Unlocked T87A!**

The module has been unlocked and programmed for the VIN supplied in the order.

**If you have purchased the TCM for a 2017+ Chevrolet Silverado/GMC Sierra 6.6L Duramax (L5P),** please install the TCM at this time. There are no additional steps to be completed.

**If you purchased the TCM for ANY vehicle besides a 2017+ Chevrolet Silverado/GMC Sierra 6.6L Duramax (L5P),** please read the following steps before installing your new TCM:

**Step 1:** Download and install the latest VCM Suite 4.3 Beta available at [www.hptuners.com/downloads](http://www.hptuners.com/downloads)

**Step 2:** Perform the “Replace TCM” special function in VCM Scanner

- 1) Connect VCM Scanner to the vehicle with the **stock TCM installed**
  - a. Go to “Vehicle Controls & Special Functions”
  - b. Click “Replace TCM” to start the function (located under System -> General)
  - c. Follow the prompts to complete the Replace TCM process for the stock TCM
- 2) When prompted, replace the stock TCM with the HP Tuners unlocked one
- 3) Connect VCM Scanner to the vehicle with the **unlocked TCM installed**
  - a. Go to “Vehicle Controls & Special Functions”
  - b. Click “Replace TCM” to start the function (located under System -> General)
  - c. Follow the prompts to complete the Replace TCM process for the unlocked TCM

**HP Tuners, LLC.**

701 Dartmouth Lane  
Buffalo Grove, IL 60089, USA

[www.hptuners.com](http://www.hptuners.com)  
<https://support.hptuners.com/>

