



DC: 20190505v3

Thank you for purchasing the **HP Tuners Unlocked T87A!**

The module has been unlocked and programmed for the VIN supplied in the order.

If you have purchased the TCM for a 2017+ Chevrolet Silverado/GMC Sierra 6.6L Duramax (L5P), please install the TCM at this time. There are no additional steps to be completed.

If you purchased the TCM for ANY vehicle besides a 2017+ Chevrolet Silverado/GMC Sierra 6.6L Duramax (L5P), please read the following steps before installing your new TCM:

Step 1: Download and install the latest VCM Suite 4.5 Beta available at www.hptuners.com/downloads

Step 2: Perform the “Replace TCM” special function in VCM Scanner

- 1) Connect VCM Scanner to the vehicle with the **stock TCM installed**
 - a. Go to “Vehicle Controls & Special Functions”
 - b. Click “Replace TCM” to start the function (located under System -> General)
 - c. Follow the prompts to complete the Replace TCM process for the stock TCM
- 2) When prompted, replace the stock TCM with the HP Tuners unlocked one
- 3) Connect VCM Scanner to the vehicle with the **unlocked TCM installed**
 - a. Go to “Vehicle Controls & Special Functions”
 - b. Click “Replace TCM” to start the function (located under System -> General)
 - c. Follow the prompts to complete the Replace TCM process for the unlocked TCM

HP Tuners, LLC.

700 Eastwood Lane
Buffalo Grove, IL 60089, USA

www.hptuners.com
<https://support.hptuners.com/>

